

दिल्ली नगर निगम



MUNICIPAL CORPORATION OF DELHI

Office of the Assistant Engineer (Bldg.)
Shahdara South Zone
KARKARDOOMA DELHI

No. 1089/EE(B)09

dt 23/3/09

Building fitness certificate

This is certified that the structural part of the Amity International senior secondary school building at site No.-2, Mayur Vihar Ph-1, Delhi is pucca sound & safe for running a school. This certificate is issued on the basis of structural safety certificate given by structural engineer & inspection of the building. The certificate is only meant for structural safety.

Mr. B.N Bajpai
Manager

Ms. Meenu Kanwar
Principal
AIS, Mayur Vihar

23/3/09
Assistant Engineer

Assistant Engineer (I)
Shahdara South Z
M.C.D.